



Business Paper

Consultative Traffic Forum

Friday, 6 April 2018

8.30am

**Committee Rooms 202 and 203,
Level 2, Administration Building,
4-20 Eton Street, Sutherland**

SUTHERLANDSHIRE

ORDER OF BUSINESS

- 1. APOLOGIES**
- 2. DISCLOSURES OF INTEREST**
- 3. CONFIRMATION OF MINUTES OF THE PREVIOUS MEETING**
- 4. REPORTS FROM OFFICERS – CONSULTATIVE TRAFFIC FORUM**
CTF013-18 Changes to Parking Restrictions - Captain Cook Drive, Caringbah
- 5. ADDITIONAL MATTERS RAISED AT MEETING (if any)**

**CTF013-18 CHANGES TO PARKING RESTRICTIONS - CAPTAIN COOK DRIVE,
CARINGBAH**

Attachments: Appendix A [↓](#)

EXECUTIVE SUMMARY

- In February 2018, Roads and Maritime Service received signed community letters requesting timed parking restrictions on the northern side of Captain Cook Drive between Cawarra Road and Woodfield Boulevard in Caringbah.
- Roads and Maritime has since accepted the 2P Parking (8:30AM to 6PM Monday to Friday) kerbside parking proposal and is notifying the Committee for their information.
- The parking restrictions are expected to be installed in April 2018.

REPORT RECOMMENDATION

That the Consultative Traffic Forum be informed of the changes along Captain Cook Drive. A post consultation flyer showing the changes has been attached to the report.

LOCATION

Captain Cook Drive between Cawarra Road and Woodfield Boulevard in Caringbah.

REFERRAL TO COMMITTEE

Nil

ISSUES

Rate of parking turnover is of concern to the nearby business.

PREVIOUS CONSIDERATION BY COMMITTEE

Nil

COMMENTS FROM INVESTIGATING OFFICER

In December 2008 (Council File Reference 770592785, DMS C5/05/160090) and more recently February 2018, Roads and Maritime Services was contacted by Sutherland Shire Council and a member of the community requesting changes to parking restrictions along Captain Cooks Drive between Woodfield Boulevard and Cawarra Road in Caringbah.

Concerns were raised that the existing unrestricted parking was 'unsupportive' of the nearby businesses.

The existing kerbside parking on the northern side of the road is currently 30 metres of unrestricted parking, followed by 56 metres 'No Parking' on approach to the signalised intersection of Captain Cook Drive and Cawarra Road in Caringbah. The customer's proposal was to install 1 to 2 hour timed parking restrictions to promote kerbside parking use turn over.

Community feedback for the proposal resulted in 5 supportive signed letters and one neutral response, representing all of the nearby affected businesses.

Roads and Maritime has since accepted the proposal and will be notifying the community via letter. The installation of 30 metre (6 car spaces) of '2P Parking, 8:30AM to 6PM, Monday to Friday' is expected by end of April 2018.

FINANCIAL / RESOURCE IMPLICATIONS

All costs of the minor signage works to be borne by the Roads and Maritime Services.

LIST OF APPENDICES

Changes to Parking Restrictions Captain Cook Drive, Caringbah – Flyer

RESPONSIBLE OFFICER

The officers responsible for the preparation of this Report are Team Leader – Traffic and Transport Services, Peter Warren, Sutherland Shire Council who can be contacted on 9710 0576 and; RMS Network and Safety Officer, Mark Carruthers, who can be contacted on (02) 8849 2534.

File

Number:

2018/296727



20 March 2018

Changes to Parking Restrictions Captain Cook Drive, Caringbah

In March 2018, Roads and Maritime Services invited feedback on proposed timed parking restrictions for the five parking spaces between Cawarra Road and Woodfield Blvd, on Captain Cook Drive, Caringbah.

Positive feedback was received for the proposal to change the unlimited parking spaces to either one or two hour parking.

Roads and Maritime proposed that 30m (approximately 5 cars) of kerbside parking become a 2P zone, Monday to Friday 8:30am - 6pm.

Key issues during the consultation revealed that local businesses were inconvenienced as their customers had complaints about having nowhere to park their vehicles for a short period of time. This parking is regularly taken up by employees of nearby business and advertising trailers that can remain there for extended periods of time. To alleviate this issue, short period parking restrictions should be put in place.

Roads and Maritime will have the new signs installed in the next few weeks.

We thank everyone who provided comments and the community and stakeholders for considering the proposal.

If you have any questions, please contact Mark Carruthers, Network & Safety Officer on 02 8849 2534 or mark.j.carruthers@rms.nsw.gov.au



Translating and Interpreting Service

If you need an interpreter, please call the Translating and Interpreting Service (TIS National) on **131 450** and ask them to telephone Roads and Maritime Services on 02 8849 2534

Arabic
إذا كنت بحاجة إلى مترجم، الرجاء الاتصال بخدمة الترجمة الخطية والشفوية (TIS National) على الرقم 131 450، والطلب منهم الاتصال بوكالتكم Roads and Maritime Services على الرقم 02 8849 2534

Cantonese
若你需要口譯員，請致電 131 450 聯絡翻譯和口譯服務署 (TIS National)，要求他們致電 02 8849 2534 聯絡 Roads and Maritime Services

Mandarin
如果你需要口译员，请致电 131 450 联系翻译和口译服务署 (TIS National)，要求他们致电 02 8849 2534 联系 Roads and Maritime Services。

Greek

Αν χρειάζεστε διερμηνέα, παρακαλείσθε να τηλεφωνήσετε στην Υπηρεσία Μετάφρασης και Διερμηνείας (Εθνική Υπηρεσία ΤΙΣ) στο **131 450** και ζητήστε να τηλεφωνήσουν Roads and Maritime Services στο 02 8849 2534

Italian

Se desiderate l'assistenza di un interprete, prego telefonare al Servizio Interpreti e Traduttori (TIS National) al **131 450** chiedendo di contattare Roads and Maritime Services al 02 8849 2534

Korean

통역사가 필요하시면 번역통역서비스 (TIS National) 에 **131 450** 으로 연락하여 이들에게 02 8849 2534 번으로 Roads and Maritime Services 에 전화하도록 요청하십시오.

Vietnamese

Nếu cần thông ngôn viên, xin quý vị gọi cho Dịch Vụ Thông Phiên Dịch (TIS Toàn Quốc) qua số **131 450** và nhờ họ gọi cho Roads and Maritime Services qua số 02 8849 2534





Legend

Existing

- Unrestricted Parking
- No Stopping
- No Parking

Changes

- 2P Parking Restrictions



Roads and Maritime Services

Level 44 George Street, Sydney NSW 2000 |
PO Box K659, Haymarket NSW 1240 |

www.rms.nsw.gov.au | 13 17 82



Captain Cook Drive, Caringbah 2